

# Your Trail Names Here

Survey Location, State

## Trail Survey Report

### **Prepared for:**

The name of Your Company Here  
Representative Name Here  
Mailing Address  
City, State ZIP

### **Prepared By:**

Donald R. Hays, Jr.



## **Survey Location:**

This trailhead is about 28 miles from your office on a road. Good signage from your road and at all forks. This trail starts down a steep well-signed dirt road. Trailhead is well signed and trail starts off as a road. At the trail junction there is a good barrier.

## **Description of work:**

To provide a condition survey for your company based on my Data Dictionary to determine if the trail needs reconstruction or relocation. This survey is for demonstration purposes of the associated Data Dictionary. There are no digital photographs accompanying this report, however there would be in a real report. The trails and reclaimed roads in this report are not on any topographic maps. For the most part the trails and reclaimed roads in this area are in very good condition, primarily "routine maintenance", minor rock removal and clearing, heavy in places, are all that is needed. These trails and roads are heavily used in both summer and winter. I did not encounter any motorized vehicles in this area, so the general public may be obeying the signs.

## **Condition report:**

The overall condition of this trail is very good. Lots of minor clearing needs to be done here and there, minor rock removal, and one small reroute should be done. There are segments that need work. All of this can be shown on the accompanying map. All structures are very good. The trail itself has narrowed due to no back sloping. The trail changes grades at existing trees or goes between trees that should be cut for clearance. The grades are very comfortable, steps are done well. Signage is not a problem, except where the trail from another trail comes in. A new sign should be installed or the existing trail (not very well used) could be abandoned.

The **total length** of trail in this report is: 51,912.48 feet

## Glossary of Codes

Condition Code	Condition name	Description
1	Routine maintenance	Trail feature is functioning within standards as designed and is within normal maintenance cycle. Cost is generally between 10% and 20% of replacement.
2	Repair/Rehab	Trail feature is in disrepair, may or may not be useable, but needs to be repaired to bring feature to standard. Cost generally between 21% and 50% of replacement.
3	Replace in-kind	Trail feature is dysfunctional and is beyond it's designated lifecycle or generally has deteriorated to a point where it is unable to perform as designed or constructed. Cost generally over 51% of new construction and includes demolition, restoration, and removal of existing segment or item.
4	Decommission	Trail feature is not needed for the operation of the trail, or is inappropriate for the setting and should be removed from system with no replacement.
5	Expansion	Trail feature is basically functioning as designed but is undersized. Would typically be lengthened or widened, but in some cases size may be reduced.
6	Alter function	Trail feature must be modified to change function to either increase capacity, change function, or durability.
7	Install new	Trail feature is missing or new trail feature is needed.
Soil Code	Condition name	Description
1	Fine/Organic	Trailbed soils are uniform fine texture with little or no rock content. May be dark with high organic content. Demonstrates low carrying capacity, especially when wet. Trenches easily, highly dusty when dry, highly erosive.
2	Sand	Trailbed soil may be uniform sand-grain texture with few fines. Refuses to compact when dry. Highly susceptible to erosion.
3	Pumice	Trailbed is broken cobbles with few or no fines. Does not compact. Highly susceptible to erosion, particularly with ability to float in water.
4	Common	Trailbed soil is with good mixture of clays, fines and small rocks. May be loose or highly compacted. Compacts well, good erosion resistance.
5	Common with Larger Rocks	Trailbed soil is with a good mixture of clays, fines, and small rock intermixed with larger rocks or small boulders. May be loose or highly compacted. Removal of larger rocks may include prying out, digging or breaking in place.

Soil Code	Condition name	Description
6	Talus or Boulders	Trailbed material is mostly rock of uniform or varying sizes containing little or no soil. Removal is required by hand, machine or blasting. Trail bed may be built over the top of rocks and imported materials and geotextiles used instead or removal.
7	Bedrock	Trailbed is bedrock or very large boulders, larger than a small car. Blasting is generally the only option to create a level walking surface.

Brush Code	Condition name	Description
1	None	No brush or grasses within trail corridor
2	Extra Light	Grass, light perennials, or other non-woody plants. Capable of being worked with mower or power brushcutter.
3	Light	Small brush shorter than knee height, slow growing woody brush diameter typically no greater than 1/2 inch. Capable of being cut with large mower or motorized brush cutter
4	Medium	Faster growing woody brush with diameters typically between 1/2 inch and 1 inch and heights lower than chest high. Typically cut with hand loppers, motorized brushcutter, chainsaws or specialized mower.
5	Heavy	Fast growing brush above head high with typical diameters greater than 1 inch. Typically cut with chainsaws, large brushcutters or specialized mower.
6	Extra Heavy	Very dense and fast growing brush above head high with diameters greater than 2 inches. Typically cut with chainsaws, or hand loppers.

Timber Code	Condition name	Description
1	None	Meadow or opening where no trees could fall within trail corridor.
2	Extra Light	Open scattered timber where some trees may fall into trail corridor.
3	Light	Low density (greater than 10 foot spacing) small diameter 4 inch to 12 inch trees. Trail location would avoid cutting most trees. Most likely young stable and maturing live trees.
4	Medium	Moderately dense (6-10 ft spacing) small to medium 4 inch to 18 inch diameter trees or dense (less than 6 ft spacing) small diameter trees. Dead trees starting to be noticeable. Relocations would likely require a substantial number of small to medium trees to be removed. Typically maturing to mature trees.

Timber Code	Condition name	Description
5	Heavy	Moderately dense large diameter (18 to 36 inch) trees or dense medium diameter (12 to 24 inch) trees. Dead trees may be substantial or fire burned small to medium diameter trees. Relocations would likely require removal of many medium to large diameter trees. Typically mature timber.
6	Extra Heavy	Dense medium to very large diameter (over 24 inch) trees; moderately dense very large diameter (over 36 inch) trees; or fire burned areas with dense medium to large diameter (18 to 36 inch) trees. Trail relocation would require removal of a substantial number of medium to large trees. Mature to over mature trees typical.

# Report Limitations

Please read carefully.

This report is an acknowledgement of the condition of those trails authorized to have been built by the landowner. To our knowledge we have not followed any other trails unless otherwise specified. The GPS survey is of the trailbed and all trail related items. This report *does not* include structures such as restrooms, buildings of any sort or parking lots, although they are located and identified for your information only. No items were dismantled in the trail system during the GPS survey. Utilities, both above and underground are not inspected.

This GPS survey is our opinion of the condition of the above-mentioned trail systems requested, to the best of our knowledge at the time of inspection only. Due to the fact there is no known established guidelines or diagrams for this survey, this report is primarily our opinion, based on trail building experience and upon specific trail user groups.

*This is not a user group survey.* Although the user groups are noted, it is not to restrict any user group from the trail.

This GPS survey and report does not address the possibility of trees falling on the trail. It does however locate trees blocking the trail either on the ground or across the corridor, above the trail.

Understanding that some degree of normal wear and tear are to be expected, some cosmetic considerations are not within the scope of this survey. Even the most comprehensive survey cannot be expected to reveal every condition that may be considered significant. A walkthrough may be recommended at the end of the GPS survey for you to examine the portions of the trail system that are of concern.

Items that were found to be deteriorated, broken or have failed in some way will be noted and photographed. Items that are considered to have normal wear and tear or minor damage for the age of the trail system and are serviceable will not be individually photographed, however they will be located.

This GPS survey and report are performed and prepared for the sole, confidential and exclusive use and possession of the landowner. DONALD HAYS TRAIL CONTRACTOR, INC. assumes no responsibility or liability to any third part in connection with the GPS survey or report. **THIS REPORT IS NOT TRANSFERABLE.**

Carefully review the report, which has been designed to be easy to read. Accompanying GPS data files are of the projection and format requested. Additional information can be queried from that data. If you have any questions regarding this survey please contact our office immediately. DHTC, Inc. will not be responsible for any outside labor or repair costs.

## Survey Results

The following table is my opinion of the condition of trail features in the contract. The features are either lines or points. A line has length, a point does not. Where the feature is a "line" those numbers represent segments in that condition. The number in a point is a single feature. Each box represents the number of features, or segments in that category.

	<b>Decommission</b>	<b>Install New</b>	<b>Repair/ Rehab</b>	<b>Replace in-kind</b>	<b>Routine Maint</b>
<b>Adjacent</b> Road Junction					13
<b>Adjacent</b> Trail Junction					15
<b>Adjacent</b> Trailhead					7
<b>Bridges</b> Side Girder					1
<b>Bridges</b> Single Unit					1
<b>Climbing turn</b> N/A			1		
<b>Culvert</b> Corrugated PVC					1
<b>Culvert</b> Corrugated metal		3			20
<b>Down_Tree</b>	21				
<b>Drainage</b> N/A		4	32	1	179
<b>Grid_Block</b> Type 1		8	1		4
<b>Gully Xing</b> Log Retainer					2

	<b>Decommission</b>	<b>Install New</b>	<b>Repair/ Rehab</b>	<b>Replace in-kind</b>	<b>Routine Maint</b>
<b>Gully Xing</b> No Retainer			1		9
<b>Gully Xing</b> Rock Retainer			2		6
<b>Gully Xing</b> Treated timber					1
<b>Individual step</b> Rock					2
<b>Line Segment</b> Recreational					5
<b>Line Segment</b> Transportation					4
<b>Markers_</b> Boundry Sigh			1		1
<b>Markers_</b> Guide-Destination				1	11
<b>Markers_</b> Information					3
<b>Markers_</b> Interpretive					1
<b>Markers_</b> Regulatory			1	1	12
<b>Markers_</b> Router Post				1	10
<b>Puncheon</b> Log Retainer		2			2
<b>Restriction devic</b> Barricade					4

	Decommission	Install New	Repair/ Rehab	Replace in-kind	Routine Maint
<b>Restriction device</b> Fence					1
<b>Restriction device</b> Gate					8
<b>Retaining wall</b> Stacked Rock					1
<b>Road</b> Recreational			1		48
<b>Road</b> Transportation					8
<b>Stairway</b> Rock Stairway			1		2
<b>Stream Ford</b> No retainer			4		3
<b>Stream Ford</b> Rock retainer					20
<b>Switchback</b> Type 1			1		2
<b>Switchback</b> Type 2					5
<b>Switchback</b> Type 3					1
<b>Trail</b> Recreational			25		146
<b>Turnpike</b> Wood retainer					1
<b>Waterbar</b> Native Log				2	

	<b>Decommission</b>	<b>Install New</b>	<b>Repair/ Rehab</b>	<b>Replace in-kind</b>	<b>Routine Maint</b>
<b>Waterbar</b> Rock		1	3		24
<b>Waterbar</b> Treated timber					8

The following tables are break downs of the grade of the trail and how many segments and their lengths in feet are in each

	00% - 05%	05.1% - 08%	08.1% - 10%	10.1% - 12%	12.1% - 20%	20.1% - 30%
<b>Ped, Equest.</b> Recreational	7	4	4	3	2	2
<b>Ped., Bicycle</b> Recreational	19	9	12	5	4	
<b>Pedestrian</b> Recreational	47	24	20	7	4	

	00% - 05%	05.1% - 08%	08.1% - 10%	10.1% - 12%	12.1% - 20%	20.1% - 30%
<b>Ped, Equest.</b> Recreational	705.48	575.78	309.01	536.93	327.95	203.15
<b>Ped., Bicycle</b> Recreational	4,885.52	1,469.16	2,721.45	1,069.63	546.39	
<b>Pedestrian</b> Recreational	7,422.46	2,744.61	2,319.59	773.94	526.46	

	Repair/ Rehab	Routine Maint				
<b>Ped, Equest.</b> Recreational	1,360.18	1,298.12				
<b>Ped., Bicycle</b> Recreational	615.88	10,076.26				
<b>Pedestrian</b> Recreational	871.35	12,915.69				

This is a break down of the soil type and condition.

	Repair/ Rehab	Routine Maint				
<b>Trail</b> Common	656.49	9,101.98				
<b>Trail</b> Common w/ Rock	2,190.93	15,107.47				

	Repair/ Rehab	Routine Maint				
<b>Trail</b> Talus or Boulders		80.63				

The next tables are breakdowns of the additional "line types" broken down by their type and their conditions, summarized by their total lengths in feet.

	Routine Maint					
<b>Bridges</b> Deck Girder Concrete Metal	131.08					

	Install New	Repair/ Rehab	Routine Maint			
<b>Grid_Block</b> Type 1 13- 18		14.93	48.58			
<b>Grid_Block</b> Type 1 19- 24	562.88		30.62			

	Repair/ Rehab	Routine Maint				
<b>Line Segment</b> Recreational Native Material		1,032.74				
<b>Line Segment</b> Transportation Aggregate Surfa		65.71				
<b>Line Segment</b> Transportation Asphalt		479.81				
<b>Line Segment</b> Transportation Native Material		136.31				
<b>Road</b> Recreational Aggregate Surfa		1,271.39				
<b>Road</b> Recreational Native Material	778.12	9,627.93				
<b>Road</b> Transportation Native Material		3,479.10				

	<b>Install New</b>	<b>Routine Maint</b>				
<b>Puncheon</b> Log Retainer 19- 24		103.67				
<b>Puncheon</b> Log Retainer 25-36	24.37					

	<b>Routine Maint</b>					
<b>Retaining wall</b> Stacked Rock	19.16					

	<b>Repair/ Rehab</b>	<b>Routine Maint</b>				
<b>Stairway</b> Rock Stairway 19- 24	15.40	25.24				

	<b>Routine Maint</b>					
<b>Turnpike</b> Wood retainer 19- 24	26.27					

**The following table is a list of features in the order they appear on the trail, and their condition**

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
1	Retaining wall	Stacked Rock	Routine Maint	10.00
2	Drainage	N/A	Routine Maint	
3	Trail	Recreational	Routine Maint	122.80
4	Trail	Recreational	Routine Maint	126.76
5	Drainage	N/A	Routine Maint	
6	Drainage	N/A	Routine Maint	
7	Drainage	N/A	Routine Maint	
8	Trail	Recreational	Routine Maint	27.70
9	Trail	Recreational	Routine Maint	162.17
10	Drainage	N/A	Routine Maint	
11	Drainage	N/A	Routine Maint	
12	Trail	Recreational	Routine Maint	201.28
13	Trail	Recreational	Routine Maint	256.73
14	Trail	Recreational	Routine Maint	102.07
15	Trail	Recreational	Routine Maint	198.61
16	Trail	Recreational	Repair/ Rehab	106.79
17	Gully Xing	No Retainer	Routine Maint	
18	Stream Ford	Rock retainer	Routine Maint	
19	Trail	Recreational	Routine Maint	87.80
20	Trail	Recreational	Routine Maint	212.05
21	Gully Xing	Treated timber	Routine Maint	
22	Gully Xing	No Retainer	Routine Maint	
23	Gully Xing	No Retainer	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
24	Gully Xing	No Retainer	Routine Maint	
25	Drainage	N/A	Repair/ Rehab	
26	Trail	Recreational	Routine Maint	40.84
27	Trail	Recreational	Routine Maint	42.99
28	Trail	Recreational	Routine Maint	207.81
29	Down_Tree		Decommission	1.00
30	Drainage	N/A	Repair/ Rehab	
31	Drainage	N/A	Repair/ Rehab	
32	Down_Tree		Decommission	1.00
33	Trail	Recreational	Routine Maint	97.66
34	Grid_Block	Type 1	Routine Maint	48.58
35	Stream Ford	Rock retainer	Routine Maint	
36	Grid_Block	Type 1	Repair/ Rehab	14.93
37	Trail	Recreational	Routine Maint	134.73
38	Down_Tree		Decommission	2.00
39	Trail	Recreational	Repair/ Rehab	98.22
40	Trail	Recreational	Routine Maint	39.77
41	Trail	Recreational	Routine Maint	341.82
42	Gully Xing	Rock Retainer	Routine Maint	
43	Trail	Recreational	Routine Maint	140.06
44	Restriction device	Barricade	Routine Maint	
45	Trail	Recreational	Routine Maint	180.40
46	Trail	Recreational	Repair/ Rehab	76.15
47	Grid_Block	Type 1	Install New	60.65
48	Trail	Recreational	Repair/ Rehab	321.32

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
49	Grid_Block	Type 1	Install New	15.41
50	Trail	Recreational	Repair/ Rehab	16.38
51	Restriction device	Barricade	Routine Maint	
52	Trail	Recreational	Repair/ Rehab	66.67
53	Down_Tree		Decommission	2.00
54	Trail	Recreational	Routine Maint	146.89
55	Drainage	N/A	Repair/ Rehab	
56	Trail	Recreational	Routine Maint	174.81
57	Trail	Recreational	Routine Maint	63.76
58	Stream Ford	Rock retainer	Routine Maint	
59	Stream Ford	Rock retainer	Routine Maint	
60	Trail	Recreational	Routine Maint	93.03
61	Markers_	Guide-Destination	Routine Maint	
62	Gully Xing	No Retainer	Routine Maint	
63	Culvert	Corrugated metal	Routine Maint	
64	Culvert	Corrugated metal	Routine Maint	
65	Trail	Recreational	Routine Maint	36.39
66	Trail	Recreational	Routine Maint	90.92
67	Gully Xing	No Retainer	Routine Maint	
68	Drainage	N/A	Repair/ Rehab	
69	Trail	Recreational	Routine Maint	455.73
70	Adjacent	Trail Junction	Routine Maint	
71	Restriction device	Barricade	Routine Maint	
72	Trail	Recreational	Routine Maint	301.50
73	Drainage	N/A	Repair/ Rehab	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
74	Puncheon	Log Retainer	Routine Maint	56.36
75	Drainage	N/A	Routine Maint	
76	Drainage	N/A	Routine Maint	
77	Drainage	N/A	Routine Maint	
78	Drainage	N/A	Routine Maint	
79	Grid_Block	Type 1	Routine Maint	10.76
80	Grid_Block	Type 1	Routine Maint	4.58
81	Trail	Recreational	Routine Maint	99.01
82	Grid_Block	Type 1	Install New	108.48
83	Turnpike	Wood retainer	Routine Maint	19.81
84	Grid_Block	Type 1	Install New	141.78
85	Down_Tree		Decommission	1.00
86	Trail	Recreational	Routine Maint	122.99
87	Grid_Block	Type 1	Install New	80.08
88	Trail	Recreational	Routine Maint	19.81
89	Puncheon	Log Retainer	Routine Maint	47.31
90	Drainage	N/A	Routine Maint	
91	Drainage	N/A	Routine Maint	
92	Drainage	N/A	Routine Maint	
93	Drainage	N/A	Routine Maint	
94	Drainage	N/A	Routine Maint	
95	Grid_Block	Type 1	Install New	17.55
96	Drainage	N/A	Routine Maint	
97	Trail	Recreational	Routine Maint	65.48
98	Grid_Block	Type 1	Install New	21.18

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
99	Drainage	N/A	Routine Maint	
100	Trail	Recreational	Routine Maint	71.01
101	Drainage	N/A	Routine Maint	
102	Drainage	N/A	Routine Maint	
103	Trail	Recreational	Routine Maint	110.19
104	Grid_Block	Type 1	Routine Maint	15.28
105	Drainage	N/A	Routine Maint	
106	Trail	Recreational	Routine Maint	101.47
107	Drainage	N/A	Repair/ Rehab	
108	Drainage	N/A	Repair/ Rehab	
109	Drainage	N/A	Repair/ Rehab	
110	Trail	Recreational	Routine Maint	149.05
111	Drainage	N/A	Repair/ Rehab	
112	Drainage	N/A	Repair/ Rehab	
113	Drainage	N/A	Repair/ Rehab	
114	Markers_	Guide-Destination	Routine Maint	
115	Adjacent	Trail Junction	Routine Maint	
116	Trail	Recreational	Routine Maint	203.63
117	Drainage	N/A	Routine Maint	
118	Trail	Recreational	Routine Maint	769.02
119	Drainage	N/A	Repair/ Rehab	
120	Drainage	N/A	Repair/ Rehab	
121	Trail	Recreational	Routine Maint	72.57
122	Trail	Recreational	Routine Maint	412.33
123	Trail	Recreational	Routine Maint	177.43

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
124	Drainage	N/A	Routine Maint	
125	Trail	Recreational	Routine Maint	50.74
126	Trail	Recreational	Routine Maint	53.42
127	Trail	Recreational	Routine Maint	299.29
128	Drainage	N/A	Routine Maint	
129	Adjacent	Trail Junction	Routine Maint	
130	Markers_	Guide-Destination	Routine Maint	
131	Stream Ford	Rock retainer	Routine Maint	
132	Trail	Recreational	Routine Maint	117.88
133	Waterbar	Rock	Routine Maint	37.00
134	Waterbar	Rock	Install New	37.00
135	Adjacent	Trail Junction	Routine Maint	
136	Trail	Recreational	Routine Maint	95.17
137	Road	Recreational	Routine Maint	454.13
138	Drainage	N/A	Routine Maint	36.00
139	Restriction device	Gate	Routine Maint	
140	Markers_	Guide-Destination	Replace in-kind	
141	Drainage	N/A	Routine Maint	36.00
142	Drainage	N/A	Repair/ Rehab	36.00
143	Drainage	N/A	Routine Maint	36.00
144	Drainage	N/A	Routine Maint	36.00
145	Drainage	N/A	Routine Maint	36.00
146	Road	Recreational	Routine Maint	178.39
147	Drainage	N/A	Routine Maint	36.00
148	Markers_	Regulatory	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
149	Road	Recreational	Routine Maint	182.71
150	Drainage	N/A	Routine Maint	36.00
151	Drainage	N/A	Routine Maint	36.00
152	Drainage	N/A	Routine Maint	
153	Road	Recreational	Routine Maint	338.86
154	Drainage	N/A	Routine Maint	
155	Drainage	N/A	Routine Maint	
156	Drainage	N/A	Routine Maint	
157	Drainage	N/A	Routine Maint	
158	Drainage	N/A	Routine Maint	
159	Road	Recreational	Routine Maint	168.35
160	Drainage	N/A	Routine Maint	36.00
161	Drainage	N/A	Routine Maint	
162	Gully Xing	No Retainer	Routine Maint	
163	Drainage	N/A	Routine Maint	
164	Road	Recreational	Routine Maint	583.34
165	Drainage	N/A	Routine Maint	
166	Drainage	N/A	Routine Maint	
167	Drainage	N/A	Routine Maint	
168	Drainage	N/A	Routine Maint	
169	Drainage	N/A	Routine Maint	
170	Drainage	N/A	Routine Maint	
171	Drainage	N/A	Install New	
172	Drainage	N/A	Install New	
173	Drainage	N/A	Install New	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
174	Drainage	N/A	Install New	
175	Markers_	Guide-Destination	Routine Maint	
176	Line Segment	Recreational	Routine Maint	146.74
177	Markers_	Information	Routine Maint	
178	Markers_	Regulatory	Routine Maint	
179	Restriction device	Barricade	Routine Maint	
180	Drainage	N/A	Repair/ Rehab	
181	Drainage	N/A	Routine Maint	
182	Line Segment	Recreational	Routine Maint	126.00
183	Drainage	N/A	Routine Maint	
184	Drainage	N/A	Routine Maint	
185	Line Segment	Recreational	Routine Maint	68.57
186	Drainage	N/A	Routine Maint	
187	Drainage	N/A	Routine Maint	
188	Line Segment	Recreational	Routine Maint	179.31
189	Drainage	N/A	Routine Maint	
190	Drainage	N/A	Routine Maint	48.00
191	Drainage	N/A	Routine Maint	48.00
192	Line Segment	Recreational	Routine Maint	512.13
193	Drainage	N/A	Routine Maint	48.00
194	Drainage	N/A	Routine Maint	48.00
195	Drainage	N/A	Routine Maint	48.00
196	Drainage	N/A	Routine Maint	48.00
197	Drainage	N/A	Routine Maint	48.00
198	Adjacent	Trail Junction	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
199	Markers_	Guide-Destination	Routine Maint	
200	Drainage	N/A	Routine Maint	48.00
201	Drainage	N/A	Routine Maint	48.00
202	Markers_	Regulatory	Routine Maint	
203	Drainage	N/A	Routine Maint	48.00
204	Drainage	N/A	Routine Maint	96.00
205	Restriction device	Gate	Routine Maint	
206	Adjacent	Road Junction	Routine Maint	
207	Trail	Recreational	Routine Maint	2.23
208	Stairway	Rock Stairway	Routine Maint	7.87
209	Trail	Recreational	Routine Maint	68.91
210	Drainage	N/A	Routine Maint	12.00
211	Trail	Recreational	Routine Maint	173.92
212	Drainage	N/A	Routine Maint	12.00
213	Trail	Recreational	Routine Maint	76.89
214	Markers_	Regulatory	Routine Maint	
215	Grid_Block	Type 1	Install New	117.77
216	Stream Ford	No retainer	Repair/ Rehab	
217	Stream Ford	No retainer	Repair/ Rehab	
218	Stream Ford	No retainer	Repair/ Rehab	
219	Stream Ford	No retainer	Repair/ Rehab	
220	Trail	Recreational	Routine Maint	42.03
221	Adjacent	Road Junction	Routine Maint	
222	Trail	Recreational	Routine Maint	270.98
223	Trail	Recreational	Routine Maint	121.08

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
224	Trail	Recreational	Routine Maint	178.42
225	Drainage	N/A	Routine Maint	18.00
226	Trail	Recreational	Repair/ Rehab	85.28
227	Trail	Recreational	Repair/ Rehab	100.55
228	Trail	Recreational	Routine Maint	263.30
229	Restriction device	Gate	Routine Maint	
230	Markers_	Regulatory	Routine Maint	
231	Adjacent	Road Junction	Routine Maint	
232	Trail	Recreational	Routine Maint	135.08
233	Markers_	Guide-Destination	Routine Maint	
234	Trail	Recreational	Routine Maint	66.01
235	Trail	Recreational	Routine Maint	180.76
236	Drainage	N/A	Routine Maint	24.00
237	Drainage	N/A	Routine Maint	24.00
238	Drainage	N/A	Routine Maint	24.00
239	Stairway	Rock Stairway	Routine Maint	17.36
240	Trail	Recreational	Routine Maint	214.65
241	Drainage	N/A	Routine Maint	24.00
242	Drainage	N/A	Routine Maint	24.00
243	Trail	Recreational	Routine Maint	43.42
244	Trail	Recreational	Routine Maint	70.35
245	Trail	Recreational	Routine Maint	77.18
246	Trail	Recreational	Routine Maint	47.42
247	Trail	Recreational	Routine Maint	113.19
248	Drainage	N/A	Routine Maint	24.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
249	Markers_	Guide-Destination	Routine Maint	
250	Trail	Recreational	Routine Maint	28.25
251	Trail	Recreational	Routine Maint	0.20
252	Trail	Recreational	Routine Maint	33.21
253	Trail	Recreational	Routine Maint	11.53
254	Trail	Recreational	Routine Maint	27.32
255	Drainage	N/A	Routine Maint	
256	Trail	Recreational	Routine Maint	127.23
257	Drainage	N/A	Routine Maint	
258	Trail	Recreational	Routine Maint	52.60
259	Trail	Recreational	Routine Maint	84.61
260	Trail	Recreational	Routine Maint	425.15
261	Trail	Recreational	Routine Maint	154.00
262	Trail	Recreational	Routine Maint	170.26
263	Switchback	Type 1	Routine Maint	10.00
264	Trail	Recreational	Routine Maint	301.92
265	Switchback	Type 1	Routine Maint	10.00
266	Waterbar	Rock	Routine Maint	
267	Trail	Recreational	Routine Maint	168.20
268	Markers_	Guide-Destination	Routine Maint	
269	Adjacent	Trail Junction	Routine Maint	
270	Markers_	Boundry Sigh	Routine Maint	
271	Markers_	Guide-Destination	Routine Maint	
272	Gully Xing	Rock Retainer	Routine Maint	
273	Line Segment	Transportation	Routine Maint	65.71

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
274	Markers_	Router Post	Routine Maint	
275	Restriction device	Fence	Routine Maint	
276	Line Segment	Transportation	Routine Maint	136.31
277	Line Segment	Transportation	Routine Maint	273.20
278	Markers_	Router Post	Routine Maint	
279	Culvert	Corrugated PVC	Routine Maint	
280	Markers_	Router Post	Routine Maint	
281	Restriction device	Gate	Routine Maint	
282	Markers_	Information	Routine Maint	
283	Markers_	Regulatory	Routine Maint	
284	Markers_	Router Post	Routine Maint	
285	Line Segment	Transportation	Routine Maint	206.61
286	Markers_	Guide-Destination	Routine Maint	
287	Markers_	Router Post	Routine Maint	
288	Adjacent	Trail Junction	Routine Maint	
289	Bridges	Side Girder	Routine Maint	37.35
290	Trail	Recreational	Routine Maint	39.71
291	Trail	Recreational	Routine Maint	447.33
292	Markers_	Interpretive	Routine Maint	
293	Adjacent	Trail Junction	Routine Maint	
294	Trail	Recreational	Routine Maint	86.42
295	Trail	Recreational	Routine Maint	14.00
296	Road	Recreational	Routine Maint	310.08
297	Restriction device	Gate	Routine Maint	
298	Markers_	Guide-Destination	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
299	Markers_	Regulatory	Repair/ Rehab	
300	Drainage	N/A	Routine Maint	
301	Road	Recreational	Routine Maint	38.58
302	Culvert	Corrugated metal	Routine Maint	
303	Road	Recreational	Routine Maint	25.75
304	Drainage	N/A	Routine Maint	
305	Road	Recreational	Routine Maint	547.77
306	Drainage	N/A	Routine Maint	
307	Drainage	N/A	Routine Maint	
308	Drainage	N/A	Routine Maint	
309	Drainage	N/A	Routine Maint	
310	Drainage	N/A	Routine Maint	
311	Drainage	N/A	Routine Maint	
312	Drainage	N/A	Routine Maint	
313	Drainage	N/A	Routine Maint	
314	Road	Recreational	Routine Maint	464.72
315	Drainage	N/A	Routine Maint	
316	Drainage	N/A	Routine Maint	
317	Drainage	N/A	Routine Maint	
318	Drainage	N/A	Routine Maint	
319	Drainage	N/A	Routine Maint	
320	Drainage	N/A	Routine Maint	
321	Road	Recreational	Routine Maint	184.97
322	Drainage	N/A	Routine Maint	
323	Culvert	Corrugated metal	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
324	Culvert	Corrugated metal	Routine Maint	
325	Culvert	Corrugated metal	Routine Maint	
326	Drainage	N/A	Routine Maint	
327	Trail	Recreational	Routine Maint	51.86
328	Drainage	N/A	Routine Maint	
329	Trail	Recreational	Routine Maint	25.77
330	Trail	Recreational	Routine Maint	199.49
331	Drainage	N/A	Routine Maint	
332	Drainage	N/A	Repair/ Rehab	
333	Down_Tree		Decommission	1.00
334	Drainage	N/A	Repair/ Rehab	
335	Trail	Recreational	Routine Maint	215.98
336	Drainage	N/A	Repair/ Rehab	
337	Drainage	N/A	Repair/ Rehab	
338	Trail	Recreational	Routine Maint	603.53
339	Drainage	N/A	Repair/ Rehab	
340	Drainage	N/A	Routine Maint	
341	Drainage	N/A	Routine Maint	
342	Drainage	N/A	Routine Maint	
343	Trail	Recreational	Routine Maint	122.28
344	Drainage	N/A	Routine Maint	
345	Drainage	N/A	Routine Maint	
346	Trail	Recreational	Routine Maint	58.28
347	Trail	Recreational	Routine Maint	312.35
348	Drainage	N/A	Repair/ Rehab	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
349	Drainage	N/A	Routine Maint	
350	Road	Recreational	Routine Maint	79.49
351	Culvert	Corrugated metal	Routine Maint	
352	Drainage	N/A	Routine Maint	
353	Road	Recreational	Routine Maint	86.14
354	Drainage	N/A	Routine Maint	
355	Drainage	N/A	Routine Maint	
356	Road	Recreational	Routine Maint	342.55
357	Drainage	N/A	Routine Maint	
358	Drainage	N/A	Routine Maint	
359	Down_Tree		Decommission	1.00
360	Drainage	N/A	Routine Maint	
361	Drainage	N/A	Routine Maint	
362	Drainage	N/A	Routine Maint	
363	Adjacent	Road Junction	Routine Maint	
364	Trail	Recreational	Routine Maint	531.41
365	Drainage	N/A	Routine Maint	
366	Drainage	N/A	Routine Maint	
367	Drainage	N/A	Routine Maint	
368	Trail	Recreational	Routine Maint	762.97
369	Drainage	N/A	Routine Maint	
370	Drainage	N/A	Routine Maint	
371	Drainage	N/A	Routine Maint	
372	Drainage	N/A	Routine Maint	
373	Drainage	N/A	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
374	Down_Tree		Decommission	1.00
375	Drainage	N/A	Routine Maint	
376	Drainage	N/A	Routine Maint	
377	Trail	Recreational	Routine Maint	244.22
378	Trail	Recreational	Routine Maint	223.60
379	Trail	Recreational	Routine Maint	106.82
380	Trail	Recreational	Routine Maint	21.72
381	Trail	Recreational	Routine Maint	148.92
382	Trail	Recreational	Routine Maint	68.56
383	Trail	Recreational	Routine Maint	192.12
384	Trail	Recreational	Routine Maint	135.84
385	Drainage	N/A	Routine Maint	60.00
386	Drainage	N/A	Routine Maint	60.00
387	Drainage	N/A	Routine Maint	60.00
388	Trail	Recreational	Routine Maint	38.83
389	Trail	Recreational	Routine Maint	422.58
390	Trail	Recreational	Routine Maint	54.24
391	Trail	Recreational	Routine Maint	16.76
392	Adjacent	Trailhead	Routine Maint	
393	Trail	Recreational	Routine Maint	105.54
394	Trail	Recreational	Routine Maint	544.29
395	Stream Ford	No retainer	Routine Maint	
396	Culvert	Corrugated metal	Routine Maint	
397	Trail	Recreational	Routine Maint	104.74
398	Culvert	Corrugated metal	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
399	Trail	Recreational	Routine Maint	398.36
400	Culvert	Corrugated metal	Routine Maint	
401	Stream Ford	No retainer	Routine Maint	
402	Adjacent	Trail Junction	Routine Maint	
403	Markers_	Regulatory	Routine Maint	
404	Stream Ford	Rock retainer	Routine Maint	
405	Stream Ford	Rock retainer	Routine Maint	
406	Trail	Recreational	Routine Maint	171.85
407	Stream Ford	Rock retainer	Routine Maint	
408	Trail	Recreational	Routine Maint	99.53
409	Trail	Recreational	Routine Maint	284.00
410	Trail	Recreational	Routine Maint	230.47
411	Gully Xing	Rock Retainer	Routine Maint	
412	Trail	Recreational	Routine Maint	286.78
413	Stream Ford	Rock retainer	Routine Maint	
414	Trail	Recreational	Routine Maint	22.08
415	Trail	Recreational	Routine Maint	44.70
416	Trail	Recreational	Routine Maint	696.10
417	Gully Xing	Log Retainer	Routine Maint	
418	Stream Ford	Rock retainer	Routine Maint	
419	Gully Xing	Rock Retainer	Routine Maint	
420	Down_Tree		Decommission	1.00
421	Down_Tree		Decommission	1.00
422	Gully Xing	Log Retainer	Routine Maint	
423	Waterbar	Native Log	Replace in-kind	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
424	Down_Tree		Decommission	1.00
425	Adjacent	Road Junction	Routine Maint	
426	Road	Recreational	Routine Maint	136.87
427	Adjacent	Trailhead	Routine Maint	
428	Road	Recreational	Routine Maint	39.40
429	Trail	Recreational	Routine Maint	97.94
430	Adjacent	Trailhead	Routine Maint	
431	Markers_	Regulatory	Routine Maint	
432	Drainage	N/A	Routine Maint	60.00
433	Climbing turn	N/A	Repair/ Rehab	6.00
434	Drainage	N/A	Routine Maint	60.00
435	Trail	Recreational	Routine Maint	47.37
436	Drainage	N/A	Routine Maint	12.00
437	Drainage	N/A	Routine Maint	12.00
438	Trail	Recreational	Routine Maint	101.22
439	Drainage	N/A	Routine Maint	12.00
440	Drainage	N/A	Routine Maint	12.00
441	Switchback	Type 1	Repair/ Rehab	6.00
442	Drainage	N/A	Routine Maint	12.00
443	Trail	Recreational	Routine Maint	39.06
444	Drainage	N/A	Routine Maint	12.00
445	Road	Recreational	Routine Maint	23.25
446	Road	Recreational	Routine Maint	59.21
447	Markers_	Router Post	Routine Maint	
448	Trail	Recreational	Routine Maint	38.42

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
449	Trail	Recreational	Routine Maint	168.11
450	Markers_	Regulatory	Routine Maint	
451	Markers_	Router Post	Routine Maint	
452	Adjacent	Trail Junction	Routine Maint	
453	Gully Xing	Rock Retainer	Routine Maint	
454	Trail	Recreational	Routine Maint	103.96
455	Trail	Recreational	Routine Maint	47.70
456	Trail	Recreational	Routine Maint	65.28
457	Trail	Recreational	Routine Maint	168.72
458	Gully Xing	Rock Retainer	Routine Maint	
459	Trail	Recreational	Routine Maint	217.98
460	Markers_	Router Post	Routine Maint	
461	Trail	Recreational	Routine Maint	8.58
462	Road	Recreational	Routine Maint	76.50
463	Markers_	Regulatory	Routine Maint	
464	Road	Recreational	Routine Maint	109.98
465	Drainage	N/A	Routine Maint	96.00
466	Road	Recreational	Routine Maint	225.82
467	Drainage	N/A	Repair/ Rehab	96.00
468	Drainage	N/A	Routine Maint	96.00
469	Drainage	N/A	Routine Maint	96.00
470	Drainage	N/A	Routine Maint	96.00
471	Road	Recreational	Routine Maint	144.11
472	Drainage	N/A	Repair/ Rehab	96.00
473	Drainage	N/A	Routine Maint	96.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
474	Road	Recreational	Routine Maint	37.54
475	Drainage	N/A	Repair/ Rehab	96.00
476	Road	Recreational	Routine Maint	172.05
477	Drainage	N/A	Routine Maint	96.00
478	Road	Recreational	Routine Maint	482.44
479	Drainage	N/A	Routine Maint	96.00
480	Drainage	N/A	Routine Maint	96.00
481	Road	Recreational	Routine Maint	117.12
482	Road	Recreational	Routine Maint	368.20
483	Drainage	N/A	Routine Maint	96.00
484	Drainage	N/A	Repair/ Rehab	96.00
485	Road	Recreational	Routine Maint	157.63
486	Road	Recreational	Routine Maint	210.88
487	Drainage	N/A	Repair/ Rehab	96.00
488	Road	Recreational	Routine Maint	198.42
489	Drainage	N/A	Routine Maint	96.00
490	Drainage	N/A	Repair/ Rehab	96.00
491	Road	Recreational	Routine Maint	237.38
492	Road	Recreational	Routine Maint	254.27
493	Drainage	N/A	Repair/ Rehab	96.00
494	Road	Recreational	Routine Maint	87.32
495	Drainage	N/A	Repair/ Rehab	96.00
496	Road	Recreational	Routine Maint	74.91
497	Road	Recreational	Routine Maint	23.07
498	Drainage	N/A	Repair/ Rehab	96.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
499	Trail	Recreational	Routine Maint	211.17
500	Trail	Recreational	Routine Maint	222.27
501	Down_Tree		Decommission	1.00
502	Trail	Recreational	Routine Maint	41.30
503	Trail	Recreational	Routine Maint	57.77
504	Down_Tree		Decommission	1.00
505	Trail	Recreational	Routine Maint	144.60
506	Trail	Recreational	Repair/ Rehab	160.85
507	Trail	Recreational	Routine Maint	286.33
508	Adjacent	Trail Junction	Routine Maint	
509	Trail	Recreational	Routine Maint	84.23
510	Trail	Recreational	Routine Maint	243.12
511	Road	Recreational	Routine Maint	759.71
512	Switchback	Type 2	Routine Maint	10.00
513	Switchback	Type 2	Routine Maint	10.00
514	Trail	Recreational	Routine Maint	636.27
515	Markers_	Regulatory	Routine Maint	
516	Trail	Recreational	Routine Maint	46.52
517	Stream Ford	Rock retainer	Routine Maint	
518	Trail	Recreational	Routine Maint	531.82
519	Down_Tree		Decommission	1.00
520	Gully Xing	No Retainer	Routine Maint	
521	Down_Tree		Decommission	3.00
522	Stream Ford	No retainer	Routine Maint	
523	Trail	Recreational	Routine Maint	60.89

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
524	Drainage	N/A	Routine Maint	96.00
525	Trail	Recreational	Routine Maint	338.10
526	Drainage	N/A	Routine Maint	96.00
527	Stream Ford	Rock retainer	Routine Maint	
528	Trail	Recreational	Routine Maint	45.41
529	Trail	Recreational	Routine Maint	53.53
530	Trail	Recreational	Routine Maint	35.74
531	Trail	Recreational	Routine Maint	238.13
532	Down_Tree		Decommission	1.00
533	Gully Xing	No Retainer	Repair/ Rehab	
534	Trail	Recreational	Routine Maint	145.20
535	Drainage	N/A	Routine Maint	96.00
536	Drainage	N/A	Replace in-kind	96.00
537	Trail	Recreational	Routine Maint	185.16
538	Gully Xing	Rock Retainer	Repair/ Rehab	
539	Trail	Recreational	Repair/ Rehab	257.31
540	Drainage	N/A	Routine Maint	96.00
541	Drainage	N/A	Routine Maint	96.00
542	Drainage	N/A	Routine Maint	96.00
543	Down_Tree		Decommission	1.00
544	Down_Tree		Decommission	1.00
545	Trail	Recreational	Repair/ Rehab	120.33
546	Down_Tree		Decommission	1.00
547	Waterbar	Rock	Repair/ Rehab	13.00
548	Waterbar	Rock	Repair/ Rehab	13.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
549	Trail	Recreational	Repair/ Rehab	77.40
551	Road	Transportation	Routine Maint	0.04
552	Bridges	Single Unit	Routine Maint	17.12
553	Road	Transportation	Routine Maint	1,035.95
554	Drainage	N/A	Routine Maint	96.00
555	Drainage	N/A	Routine Maint	96.00
556	Drainage	N/A	Routine Maint	96.00
557	Adjacent	Road Junction	Routine Maint	
558	Culvert	Corrugated metal	Routine Maint	
559	Culvert	Corrugated metal	Routine Maint	
560	Drainage	N/A	Routine Maint	96.00
561	Switchback	Type 2	Routine Maint	10.00
562	Road	Transportation	Routine Maint	329.75
563	Drainage	N/A	Routine Maint	96.00
564	Culvert	Corrugated metal	Routine Maint	
565	Drainage	N/A	Routine Maint	96.00
566	Drainage	N/A	Routine Maint	96.00
567	Drainage	N/A	Routine Maint	96.00
568	Switchback	Type 3	Routine Maint	10.00
569	Drainage	N/A	Routine Maint	96.00
570	Drainage	N/A	Routine Maint	96.00
571	Culvert	Corrugated metal	Routine Maint	
572	Drainage	N/A	Routine Maint	96.00
573	Road	Transportation	Routine Maint	158.53
574	Switchback	Type 2	Routine Maint	10.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
575	Switchback	Type 2	Routine Maint	10.00
576	Drainage	N/A	Routine Maint	96.00
577	Road	Transportation	Routine Maint	139.02
578	Road	Transportation	Routine Maint	244.61
579	Drainage	N/A	Routine Maint	96.00
580	Road	Transportation	Routine Maint	138.05
581	Adjacent	Road Junction	Routine Maint	
582	Drainage	N/A	Routine Maint	96.00
583	Road	Transportation	Routine Maint	1,433.16
584	Drainage	N/A	Routine Maint	96.00
585	Gully Xing	Rock Retainer	Repair/ Rehab	
586	Restriction device	Gate	Routine Maint	
587	Drainage	N/A	Routine Maint	96.00
588	Adjacent	Trailhead	Routine Maint	
589	Road	Recreational	Routine Maint	556.77
590	Restriction device	Gate	Routine Maint	
591	Drainage	N/A	Routine Maint	96.00
592	Culvert	Corrugated metal	Routine Maint	
593	Culvert	Corrugated metal	Routine Maint	
594	Stream Ford	Rock retainer	Routine Maint	
595	Trail	Recreational	Repair/ Rehab	115.75
596	Markers_	Router Post	Routine Maint	
597	Trail	Recreational	Repair/ Rehab	0.00
598	Puncheon	Log Retainer	Install New	8.64
599	Stream Ford	Rock retainer	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
600	Trail	Recreational	Repair/ Rehab	45.60
601	Trail	Recreational	Repair/ Rehab	13.37
602	Puncheon	Log Retainer	Install New	15.73
603	Culvert	Corrugated metal	Routine Maint	
604	Waterbar	Native Log	Replace in-kind	13.00
605	Trail	Recreational	Repair/ Rehab	75.31
606	Stream Ford	Rock retainer	Routine Maint	
607	Trail	Recreational	Repair/ Rehab	72.17
608	Stream Ford	Rock retainer	Routine Maint	
609	Trail	Recreational	Repair/ Rehab	251.79
610	Culvert	Corrugated metal	Routine Maint	
611	Waterbar	Rock	Routine Maint	13.00
612	Waterbar	Rock	Routine Maint	13.00
613	Trail	Recreational	Repair/ Rehab	45.79
614	Waterbar	Rock	Routine Maint	13.00
615	Waterbar	Rock	Routine Maint	13.00
616	Stream Ford	Rock retainer	Routine Maint	
617	Trail	Recreational	Repair/ Rehab	231.78
618	Stream Ford	Rock retainer	Routine Maint	
619	Stream Ford	Rock retainer	Routine Maint	
620	Culvert	Corrugated metal	Routine Maint	
621	Waterbar	Rock	Routine Maint	13.00
622	Waterbar	Rock	Routine Maint	13.00
623	Culvert	Corrugated metal	Install New	
624	Stream Ford	Rock retainer	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
625	Waterbar	Rock	Routine Maint	13.00
626	Stairway	Rock Stairway	Repair/ Rehab	15.40
627	Trail	Recreational	Repair/ Rehab	105.60
628	Waterbar	Rock	Routine Maint	13.00
629	Waterbar	Rock	Routine Maint	13.00
630	Waterbar	Rock	Routine Maint	13.00
631	Culvert	Corrugated metal	Install New	
632	Culvert	Corrugated metal	Install New	
633	Culvert	Corrugated metal	Routine Maint	
634	Trail	Recreational	Repair/ Rehab	127.36
635	Waterbar	Rock	Routine Maint	13.00
636	Individual step	Rock	Routine Maint	
637	Individual step	Rock	Routine Maint	
638	Waterbar	Rock	Repair/ Rehab	13.00
639	Waterbar	Rock	Routine Maint	13.00
640	Waterbar	Rock	Routine Maint	13.00
641	Trail	Recreational	Repair/ Rehab	179.56
642	Waterbar	Rock	Routine Maint	13.00
643	Drainage	N/A	Routine Maint	96.00
644	Drainage	N/A	Routine Maint	96.00
645	Drainage	N/A	Routine Maint	96.00
646	Waterbar	Rock	Routine Maint	13.00
647	Waterbar	Rock	Routine Maint	13.00
648	Waterbar	Rock	Routine Maint	13.00
649	Waterbar	Rock	Routine Maint	13.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
650	Waterbar	Treated timber	Routine Maint	13.00
651	Waterbar	Treated timber	Routine Maint	13.00
652	Waterbar	Rock	Routine Maint	13.00
653	Trail	Recreational	Repair/ Rehab	96.12
654	Waterbar	Treated timber	Routine Maint	13.00
655	Waterbar	Treated timber	Routine Maint	13.00
656	Waterbar	Treated timber	Routine Maint	13.00
657	Waterbar	Treated timber	Routine Maint	13.00
658	Waterbar	Treated timber	Routine Maint	13.00
659	Waterbar	Treated timber	Routine Maint	13.00
660	Waterbar	Rock	Routine Maint	13.00
661	Trail	Recreational	Routine Maint	220.29
662	Waterbar	Rock	Routine Maint	13.00
663	Waterbar	Rock	Routine Maint	13.00
664	Markers_	Information	Routine Maint	
665	Gully Xing	No Retainer	Routine Maint	
666	Adjacent	Trailhead	Routine Maint	
667	Adjacent	Road Junction	Routine Maint	
668	Road	Recreational	Routine Maint	191.75
669	Drainage	N/A	Routine Maint	96.00
670	Road	Recreational	Routine Maint	227.59
671	Markers_	Router Post	Replace in-kind	
672	Road	Recreational	Routine Maint	369.57
673	Road	Recreational	Repair/ Rehab	778.12
674	Drainage	N/A	Routine Maint	96.00

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
675	Drainage	N/A	Routine Maint	96.00
676	Drainage	N/A	Repair/ Rehab	96.00
677	Drainage	N/A	Routine Maint	96.00
678	Drainage	N/A	Routine Maint	96.00
679	Drainage	N/A	Routine Maint	96.00
680	Drainage	N/A	Routine Maint	96.00
681	Road	Recreational	Routine Maint	80.96
682	Drainage	N/A	Routine Maint	96.00
683	Road	Recreational	Routine Maint	722.45
684	Drainage	N/A	Routine Maint	
685	Adjacent	Road Junction	Routine Maint	
686	Adjacent	Trail Junction	Routine Maint	
687	Drainage	N/A	Routine Maint	
688	Adjacent	Trail Junction	Routine Maint	
689	Drainage	N/A	Routine Maint	
690	Road	Recreational	Routine Maint	113.07
691	Drainage	N/A	Routine Maint	
692	Road	Recreational	Routine Maint	245.05
693	Drainage	N/A	Routine Maint	
694	Drainage	N/A	Routine Maint	
695	Restriction device	Gate	Routine Maint	
696	Adjacent	Trailhead	Routine Maint	
697	Adjacent	Road Junction	Routine Maint	
698	Markers_	Boundry Sigh	Repair/ Rehab	
699	Adjacent	Road Junction	Routine Maint	

<b>Point ID</b>	<b>TRAIL_NAME</b>	<b>Type</b>	<b>CONDITION</b>	<b>GPS length</b>
700	Adjacent	Road Junction	Routine Maint	
701	Road	Recreational	Routine Maint	140.90
702	Adjacent	Road Junction	Routine Maint	
703	Adjacent	Trail Junction	Routine Maint	
704	Adjacent	Trail Junction	Routine Maint	
705	Down_Tree		Decommission	4.00
706	Road	Recreational	Routine Maint	68.29
707	Markers_	Router Post	Routine Maint	
708	Road	Recreational	Routine Maint	201.05
709	Markers_	Regulatory	Routine Maint	
710	Adjacent	Trailhead	Routine Maint	
711	Markers_	Regulatory	Replace in-kind	
715	Down_Tree		Decommission	1.00